

**DEMOLITION ASBESTOS SURVEY  
6131 RIVER ROAD  
NEW PORT RICHEY, FLORIDA**

**Prepared for:**

**Mr. Tyler Lillibridge  
Cross Construction Services, Inc.  
25221 Wesley Chapel Boulevard  
Lutz, Florida 33559**

**Prepared by:**

**IBC Engineering-Environmental & Construction, LLC (ZA-388)  
8875 Hidden River Parkway, Suite 300  
Tampa, FL 33637**

**February 27, 2023**

## **INDEX**

- 1.0 Asbestos Survey
  - 1.1 Introduction
  - 1.2 Site Description
  - 1.3 Purpose
  - 1.4 Scope
  - 1.5 Sampling Logic and Protocol
  - 1.6 Bulk Sample Analysis
  - 1.7 Hazard Assessment
  - 1.8 Synopsis and Recommendations

## **APPENDIX**

- A. Laboratory Asbestos Test Results
- B. Chain of Custody Forms
- C. Credentials

## **1.1 INTRODUCTION**

In accordance with written direction on February 14, 2023, Mr. Tyler Lillibridge instructed IBC Engineering-Environmental & Construction, LLC, of Tampa, Florida, to perform a demolition asbestos survey of the two buildings located at 6131 River Road, New Port Richey, Florida. The survey was conducted pursuant to the National Emissions Standards for Hazardous Air Pollutants (NESHAP) requirements. The following Survey Report details the findings of the Demolition Asbestos Survey for the referenced facility.

A preliminary site inspection was performed on February 16, 2023 with the survey being performed on the same day. Mr. Oris Voigtman conducted the survey.

## **1.2 SITE DESCRIPTION**

The subject property is comprised of a two one story buildings located at 6131 River Road, New Port Richey, Florida. The buildings were unoccupied. The building were concrete block or wood framing on a concrete foundation. The flooring was vinyl flooring, ceramic tile or concrete. The buildings had asphalt roofing on wood.

## **1.3 PURPOSE**

The purpose of conducting the survey for the subject complex is to:

- Locate and identify all types of Asbestos Containing Materials, ACM throughout the accessible areas.
- Assess the existing physical condition of the ACM and determine the relative hazards presented.
- Recommend response actions in accordance with the assigned "Hazard Priority Rating" for each type of ACM identified.
- Prioritize the ACM and physical areas in order of the specific response action required.

## **1.4 SCOPE**

The Scope of Work for this survey is as follows:

- Review available construction documents to determine potential locations of ACM and to develop sample plans.
- Conduct a field investigation to access and perform a visual inspection of all accessible areas of the units to be surveyed.
- Collect bulk samples of suspect ACM identified.
- Provide bulk sample analyses by an independent and accredited laboratory.

- Assess condition of identified ACM and assign a “Hazard Priority Rating”.
- Prioritize those materials and areas which require response actions.
- Recommend appropriate response actions.

## **1.5 SAMPLING LOGIC AND PROTOCOL**

The survey protocol involved the following sequences, where available or appropriate:

1. Interview persons to elicit information regarding building construction, use of facilities (past, present and future), number of building occupants, maintenance and custodial procedures, dates of construction, HVAC design, water systems, size of units/buildings, and other information as appropriate.
2. Review of previous inspection/survey reports, laboratory data, results, building plans, construction specifications, and other pertinent documents, if available.
3. A brief walk-through of the facility to be surveyed allowed conclusions to be made concerning the number of samples needed, access problems that were to be encountered, photographic needs, and degree of protection necessary for bulk sample collection.
4. A visual inspection was conducted to identify the locations of all suspect ACBM and physically touch the material to determine if it was to be classified as friable (easily crumbled) or non-friable. Suspect materials were then catalogued according to their intended use. These categories include surfacing materials, thermal system insulation, and miscellaneous materials. Surfacing materials include sprayed or troweled-on fireproofing, acoustical, and decorative insulation, as well as insulations used for condensate control. Thermal system insulation, or TSI, includes pipe lagging, boiler and hot water storage tank insulation, and insulation on duct, pumps, heat exchangers, or other equipment. Miscellaneous suspect materials include interior building materials on structural components, structure members, or fixtures, such as floor and ceiling tiles, asbestos-cement board, and flue pipes, that did not fall into one of the previously mentioned categories.
5. Bulk sampling was conducted in accordance with United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) and USEPA National Emission Standards for Hazardous Air Pollutants (NESHAP) protocols. These procedures required a random method, which was used to select sampling locations from each homogeneous sampling area. A homogeneous area is defined as an area of surfacing material, thermal system

insulation material, or miscellaneous material that is uniform in color and texture.

6. Bulk samples were transported to the analytical laboratory where they were logged in and assigned a unique laboratory identification number.

All samples were analyzed for asbestos content by polarized light microscopy (PLM) using the "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" found at Appendix A to Subpart F in EPA 600/M-4-020. In this method the presence of asbestos in a sample was determined by optical mineralogy using a light microscope with two polarizing filters. Asbestos identification was achieved by examining the morphology and optical properties of the sample. The optical properties include the color under dispersion staining, birefringence, extinction characteristic, and the sign of elongation.

Quantification was obtained by visual estimation. This method may be used for the analysis of samples containing from 0 to 100 percent asbestos. The lower limit of detection is less than 1 percent. The upper detection limit is 100 percent. Results are reported as percent asbestos by type (e.g. chrysotile, crocidolite). Additional information such as other fibrous components in the sample and the non-fibrous sample matrix may also be supplied, if available.

7. This survey report does not intend to acknowledge, imply, or warrant the inspection for Asbestos Containing Building Materials in areas not normally considered readily accessible through standard survey protocol. These areas include, but are not limited to:
  - Inaccessible spaces below floor levels
  - Materials below ground surfaces
  - Materials in areas considered inaccessible or unsafe

## 1.6 BULK SAMPLE ANALYSIS

All bulk sample analysis was performed by National Voluntary Laboratory Accreditation Program (NVLAP) accredited CEI Labs Inc., 730 SE Maynard Road, Cary, NC 27511, via Polarized Light Microscopy (PLM) coupled with dispersion staining in general accordance with EPA 600/M-4-020. A copy of the laboratory results can be found in Appendix A. Summary results were as follows:

SAMPLE #	LOCATION	SAMPLE TYPE	RESULT
1	Church roof	Asphalt shingles	NAD
2	Church roof	Asphalt shingles	NAD

SAMPLE #	LOCATION	SAMPLE TYPE	RESULT
3	Church roof	Rolled roofing	NAD
4	Church roof	Rolled roofing	NAD
5	Church exterior	Stucco	NAD
6	Church exterior	Stucco	NAD
7	Church exterior	Caulking	NAD
8	Church exterior	Caulking	NAD
9	Church front bath	Yellow flooring	NAD
10	Church front bath	Yellow flooring	NAD
<b>11</b>	<b>Church front storage</b>	<b>9" beige floor tile/mastic</b>	<b>10-5% chrysotile</b>
12	Church foyer	Popcorn ceiling texture	NAD
13	Church chapel	Popcorn ceiling texture	NAD
<b>14</b>	<b>Church chapel</b>	<b>12" beige floor tile/mastic</b>	<b>7-2% chrysotile</b>
<b>15</b>	<b>Church chapel</b>	<b>12" beige floor tile/mastic</b>	<b>7-2% chrysotile</b>
16	Church chapel	Plaster system	NAD
17	Church middle area	Plaster system	NAD
<b>18</b>	<b>Church back bath</b>	<b>Beige pattern linoleum/adhesive</b>	<b>20-2% chrysotile</b>
<b>19</b>	<b>Church back bath</b>	<b>Beige pattern linoleum/adhesive</b>	<b>20-2% chrysotile</b>
20	Church back area	Drywall system	NAD
21	Church back area	Drywall system	NAD
22	Church back area	Lay in ceiling tile	NAD
23	Church back area	Lay in ceiling tile	NAD
24	Church back area	Covebase adhesive	NAD
25	Church back area	Covebase adhesive	NAD
26	Office roof	Asphalt shingles	NAD
27	Office roof	Asphalt shingles	NAD
28	Office exterior	Caulking	NAD
29	Office exterior	Caulking	NAD
30	Office	Drywall system	NAD
31	Office	Drywall system	NAD
32	Office	Leveling compound	NAD

SAMPLE #	LOCATION	SAMPLE TYPE	RESULT
33	Office	Leveling compound	NAD
34	Office	Floor mastic	NAD
35	Office	Floor mastic	NAD
36	Office bath	Beige linoleum	NAD
37	Office bath	Beige linoleum	NAD
38	Office	Popcorn ceiling	NAD
39	Office	Popcorn ceiling	NAD

NAD- no asbestos detected

## 1.7 HAZARD ASSESSMENT

Sample results indicated that the following materials contained asbestos minerals:

ACM DESCRIPTION	LOCATION	APPROXIMATE QUANTITY	NF/F	CAT. I/II	RACM Y/N
9" beige floor tile/mastic	Front and middle areas of church (under other flooring)	2,200 sf	NF	I	N
12" beige floor tile/mastic	Church chapel	3,500 sf	NF	I	N
Beige pattern linoleum	Church back bathrooms	250 sf	NF	II	N

## 1.8 SYNOPSIS & RECOMMENDATIONS

A preliminary site inspection determined the following building components to be suspect asbestos-containing materials:

- Roofing • Flooring • Stucco • Drywall system

Laboratory analysis of representative samples for these materials determined that several building materials contained asbestos minerals. Materials identified as Category I Non-RACM that will remain in good condition during the proposed demolition/renovation activities may often remain in place during demolition/renovation. Any materials that are Category II Non-RACM or RACM or those materials that may be rendered RACM (i.e., crumbled, pulverized, or reduced to powder by the forces expected to act upon the materials during demolition/renovation) must be removed prior to any activities that will affect these materials by a Florida Licensed Asbestos Contractor. It is the contractor's responsibility to be aware of those regulations specific to the removal and disposal of ACM and ensure compliance with them. It is recommended that on-site observation of the proposed abatement or demolition processes be performed under the direction of a Florida Licensed Asbestos Consultant. A copy of this report must be present on site during any scheduled operation. This survey document is not intended as a bid document or specification for abatement.

In conclusion, it is clearly understood that IBC does not intend this report to be representative of all potential Asbestos Containing Material (ACM) in this facility and is strictly limited to the materials tested and the limitations of the laboratory testing technology methods.

**Respectfully Submitted,**

***IBC ENGINEERING-ENVIRONMENTAL & CONSTRUCTION, LLC***

A handwritten signature in black ink, appearing to read "Oris L. Voigtmann", is written over a light gray rectangular background.

Oris L. Voigtmann, CSP, FLAC AX67



# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
01 B233873.01	Asphalt Shingle	Heterogeneous Black Fibrous Bound	50%	Fiberglass	40% 10%	Tar Gravel	None Detected
02 B233873.02	Asphalt Shingle	Heterogeneous Black Fibrous Bound	50%	Fiberglass	40% 10%	Tar Gravel	None Detected
03 B233873.03	Rolled Roofing	Heterogeneous Black Fibrous Bound	50%	Fiberglass	40% 10%	Tar Gravel	None Detected
04 B233873.04	Rolled Roofing	Heterogeneous Black Fibrous Bound	50%	Fiberglass	40% 10%	Tar Gravel	None Detected
05 B233873.05	Stucco	Heterogeneous Gray,White Non-fibrous Bound			60% 35% 5%	Silicates Binder Paint	None Detected
06 B233873.06	Stucco	Heterogeneous Gray,White Non-fibrous Bound			60% 35% 5%	Silicates Binder Paint	None Detected
07 Layer 1 B233873.07	Caulking ( Type 1 )	Heterogeneous Gray,Cream Non-fibrous Bound			95% 5%	Caulk Paint	None Detected

# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS		ASBESTOS %
			Fibrous	Non-Fibrous	
Layer 2 B233873.07	Caulking ( Type 2 )	Homogeneous White Non-fibrous Bound		100% Caulk	None Detected
<b>08</b> Layer 1 B233873.08	Caulking ( Type 1 )	Heterogeneous Gray,Cream Non-fibrous Bound		95% Caulk 5% Paint	None Detected
Layer 2 B233873.08	Caulking ( Type 2 )	Homogeneous White Non-fibrous Bound		100% Caulk	None Detected
<b>09</b> B233873.09	Flooring	Homogeneous Yellow,Cream Non-fibrous Tightly Bound		70% Binder 30% Silicates	None Detected
<b>10</b> B233873.10	Flooring	Homogeneous Yellow,Cream Non-fibrous Tightly Bound		70% Binder 30% Silicates	None Detected
<b>11</b> B233873.11A	9" Floor Tile	Homogeneous Beige Non-fibrous Tightly Bound		90% Vinyl	<b>10% Chrysotile</b>
B233873.11B	Mastic	Homogeneous Black Non-fibrous Bound		95% Tar	<b>5% Chrysotile</b>

# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS		ASBESTOS %
			Fibrous	Non-Fibrous	
<b>12</b>	Popcorn Ceiling	Heterogeneous		80% Binder	None Detected
Layer 1	Texture	White		15% Foam	
B233873.12		Non-fibrous		5% Paint	
		Bound			
Layer 2	Plaster Skim Coat	Homogeneous		65% Binder	None Detected
B233873.12		White		35% Silicates	
		Non-fibrous			
		Bound			
Layer 3	Plaster Base Coat	Homogeneous		65% Silicates	None Detected
B233873.12		Gray		35% Binder	
		Non-fibrous			
		Bound			
<b>13</b>	Popcorn Ceiling	Heterogeneous		80% Binder	None Detected
Layer 1	Texture	White		15% Foam	
B233873.13		Non-fibrous		5% Paint	
		Bound			
Layer 2	Plaster Skim Coat	Homogeneous		65% Binder	None Detected
B233873.13		White		35% Silicates	
		Non-fibrous			
		Bound			
Layer 3	Plaster Base Coat	Homogeneous		65% Silicates	None Detected
B233873.13		Gray		35% Binder	
		Non-fibrous			
		Bound			
<b>14</b>	12" Floor Tile	Homogeneous		93% Vinyl	<b>7% Chrysotile</b>
B233873.14A		Beige			
		Non-fibrous			
		Tightly Bound			

# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS		ASBESTOS %
Fibrous	Non-Fibrous				
B233873.14B	Mastic	Homogeneous Yellow Non-fibrous Bound	98%	Mastic	<b>2% Chrysotile</b>
<b>15</b> B233873.15A	12" Floor Tile	Homogeneous Beige Non-fibrous Tightly Bound	93%	Vinyl	<b>7% Chrysotile</b>
B233873.15B	Mastic	Homogeneous Yellow Non-fibrous Bound	98%	Mastic	<b>2% Chrysotile</b>
<b>16</b> Layer 1 B233873.16	Plaster Skim Coat	Heterogeneous White Non-fibrous Bound	60% 35% 5%	Binder Silicates Paint	None Detected
Layer 2 B233873.16	Plaster Base Coat	Homogeneous Gray Non-fibrous Bound	65% 35%	Silicates Binder	None Detected
<b>17</b> Layer 1 B233873.17	Plaster Skim Coat	Heterogeneous White Non-fibrous Bound	60% 35% 5%	Binder Silicates Paint	None Detected
Layer 2 B233873.17	Plaster Base Coat	Homogeneous Gray Non-fibrous Bound	65% 35%	Silicates Binder	None Detected



# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
<b>18</b> B233873.18A	Linoleum	Heterogeneous Beige, Patterned Fibrous Bound	30%	Cellulose	50%	Vinyl	<b>20% Chrysotile</b>
B233873.18B	Mastic	Homogeneous White Non-fibrous Bound			98%	Mastic	<b>2% Chrysotile</b>
Analyst Opinion: Possible contamination from adjacent linoleum.							
<b>19</b> B233873.19A	Linoleum	Heterogeneous Beige, Patterned Fibrous Bound	30%	Cellulose	50%	Vinyl	<b>20% Chrysotile</b>
B233873.19B	Mastic	Homogeneous White Non-fibrous Bound			98%	Mastic	<b>2% Chrysotile</b>
Analyst Opinion: Possible contamination from adjacent linoleum.							
<b>20</b> B233873.20	Drywall/Joint Compound	Heterogeneous White, Tan Fibrous Bound	15%	Cellulose	75% 10% <1%	Gypsum Calc Carb Paint	None Detected
<b>21</b> B233873.21	Drywall/Joint Compound	Heterogeneous White, Tan Fibrous Bound	15%	Cellulose	75% 10% <1%	Gypsum Calc Carb Paint	None Detected
<b>22</b> B233873.22	Ceiling Tile	Heterogeneous White, Tan Fibrous Bound	60% 20%	Cellulose Fiberglass	15% 5%	Perlite Paint	None Detected

# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
<b>23</b> B233873.23	Ceiling Tile	Heterogeneous White, Tan Fibrous Bound	60%	Cellulose	15%	Perlite	None Detected
			20%	Fiberglass	5%	Paint	
<b>24</b> B233873.24	Covebase Adhesive	Homogeneous Cream Non-fibrous Bound			100%	Mastic	None Detected
<b>25</b> B233873.25	Covebase Adhesive	Homogeneous Cream Non-fibrous Bound			100%	Mastic	None Detected
<b>26</b> B233873.26	Asphalt Shingle	Heterogeneous Black Fibrous Bound	50%	Fiberglass	40%	Tar Gravel	None Detected
<b>27</b> B233873.27	Asphalt Shingle	Heterogeneous Black Fibrous Bound	50%	Fiberglass	40%	Tar Gravel	None Detected
<b>28</b> B233873.28	Caulking	Homogeneous Off-white Non-fibrous Bound			100%	Caulk	None Detected
<b>29</b> B233873.29	Caulking	Homogeneous Off-white Non-fibrous Bound			100%	Caulk	None Detected

## ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

### ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
<b>30</b> B233873.30	Drywall	Heterogeneous Gray, Tan Fibrous Bound	15%	Cellulose	85%	Gypsum	None Detected
<b>31</b> B233873.31	Drywall	Heterogeneous Gray, Tan Fibrous Bound	15%	Cellulose	85%	Gypsum	None Detected
<b>32</b> B233873.32	Leveling Compound	Homogeneous White Non-fibrous Bound			65% 35%	Binder Silicates	None Detected
<b>33</b> B233873.33	Leveling Compound	Homogeneous White Non-fibrous Bound			65% 35%	Binder Silicates	None Detected
<b>34</b> B233873.34	Floor Mastic	Homogeneous Black Non-fibrous Bound	5%	Cellulose	80% 15%	Tar Mastic	None Detected
<b>35</b> B233873.35	Floor Mastic	Homogeneous Black Non-fibrous Bound	5%	Cellulose	80% 15%	Tar Mastic	None Detected
<b>36</b> B233873.36A	Linoleum ( Type 1 )	Heterogeneous White Fibrous Bound	30% 20%	Cellulose Fiberglass	50%	Vinyl	None Detected

# ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

## ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS				ASBESTOS %
			Fibrous		Non-Fibrous		
B233873.36B	Mastic	Homogeneous Cream Non-fibrous Bound	5%	Cellulose	95%	Mastic	None Detected
B233873.36C	Linoleum ( Type 2 )	Heterogeneous Beige Fibrous Bound	30% 20%	Cellulose Fiberglass	50%	Vinyl	None Detected
B233873.36D	Mastic	Homogeneous Black Non-fibrous Bound	5%	Cellulose	80% 15%	Tar Mastic	None Detected
<b>37</b> B233873.37A	Linoleum ( Type 1 )	Heterogeneous White Fibrous Bound	30% 20%	Cellulose Fiberglass	50%	Vinyl	None Detected
B233873.37B	Mastic	Homogeneous Cream Non-fibrous Bound	5%	Cellulose	95%	Mastic	None Detected
B233873.37C	Linoleum ( Type 2 )	Heterogeneous Beige Fibrous Bound	30% 20%	Cellulose Fiberglass	50%	Vinyl	None Detected
<b>38</b> B233873.38	Popcorn Ceiling	Heterogeneous White Non-fibrous Bound			80% 15% 5%	Binder Metal Foil Paint	None Detected



## ASBESTOS BULK ANALYSIS

By: POLARIZING LIGHT MICROSCOPY

**Client:** O2 Consulting, Inc.  
P.O. Box 7655  
Wesley Chapel, FL 33545

**Lab Code:** B233873  
**Date Received:** 02-17-23  
**Date Analyzed:** 02-22-23  
**Date Reported:** 02-22-23

**Project:** 6131 River Road

### ASBESTOS BULK PLM, EPA 600 METHOD

Client ID Lab ID	Lab Description	Lab Attributes	NON-ASBESTOS COMPONENTS		ASBESTOS %
			Fibrous	Non-Fibrous	
39 B233873.39	Popcorn Ceiling	Heterogeneous		80% Binder	None Detected
		White		15% Metal Foil	
		Non-fibrous		5% Paint	
		Bound			

**LEGEND:** Non-Anth = Non-Asbestiform Anthophyllite  
Non-Trem = Non-Asbestiform Tremolite  
Calc Carb = Calcium Carbonate

**METHOD:** EPA 600 / R93 / 116 and EPA 600 / M4-82 / 020

**REPORTING LIMIT:** <1% by visual estimation

**REPORTING LIMIT FOR POINT COUNTS:** 0.25% by 400 Points or 0.1% by 1,000 Points

**REGULATORY LIMIT:** >1% by weight

Due to the limitations of the EPA 600 method, nonfriable organically bound materials (NOBs) such as vinyl floor tiles can be difficult to analyze via polarized light microscopy (PLM). EPA recommends that all NOBs analyzed by PLM, and found not to contain asbestos, be further analyzed by Transmission Electron Microscopy (TEM). Please note that PLM analysis of dust and soil samples for asbestos is not covered under NVLAP accreditation. *Estimated measurement of uncertainty is available on request.*

This report relates only to the samples tested or analyzed and may not be reproduced, except in full, without written approval by Eurofins CEI. Eurofins CEI makes no warranty representation regarding the accuracy of client submitted information in preparing and presenting analytical results. Interpretation of the analytical results is the sole responsibility of the client. Samples were received in acceptable condition unless otherwise noted. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Information provided by customer includes customer sample ID and sample description.

**ANALYST:** Raegan Brown  
Raegan Brown

**APPROVED BY:** Tianbao Bai  
Tianbao Bai, Ph.D., CIH  
Laboratory Director



**SAMPLE TRANSMITTAL**  
**O2 Consulting, Inc.**  
**PO Box 7655**  
**Wesley Chapel, FL 33545**

B233873

39

**PROJECT** Cel31 River Road

**TURN AROUND** 72hr

SAMPLE #	LOCATION	SAMPLE TYPE	COMMENTS
01	Cel31 roof	Asphalt shingles	
02	"	"	
03	"	rolled roofing	
04	"	"	
05	" exterior	stucco	
06	"	"	
07	"	caulking	
08	"	"	
09	" front bath	yellow flooring	walls ceramic
10	"	"	"
11	" front stage	9" barge of plaster	1200sf of back front wing areas
12	" stage	popcorn ceiling texture	4000 sf
13	Chapel	"	
14	"	12" barge FT	
15	"	"	
16	"	Plaster System	
17	" middle	"	
18	" back bath	barge pattern lwa	200 sf
19	"	"	
20	" backstage	Drywall system	
21	"	"	
22	"	lay in of	
23	"	"	
24	"	concrete adhesion	
25	"	"	
26	office pul roof	Asphalt shingles	
27	"	"	
28	" exterior	caulking	

1200sf of back  
front wing areas

**CHAIN OF CUSTODY**

Sampled by: G. A.

Date: 2/16/23

Received by: BWB

Date: 2/17 9:50

EUROFINS CEI, INC  
 SAMPLES ACCEPTED  
 BWB

8177 4374 1357

**Wesley Chapel, FL 33545**

## TURN AROUND

[illegible]

## Date: \_\_\_\_\_





Ron DeSantis, Governor

Melanie S. Griffin, Secretary



## STATE OF FLORIDA DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION

### ASBESTOS LICENSING UNIT

THE ASBESTOS CONSULTANT HEREIN IS LICENSED UNDER THE  
PROVISIONS OF CHAPTER 469, FLORIDA STATUTES

**VOIGTMANN, ORIS LEE**

IBC ENGINEERING ENVIRONMENTAL CONSTRUCTION LLC  
30949 SATINLEAF LANE  
WESLEY CHAPEL FL 33543

**LICENSE NUMBER: AX67**

**EXPIRATION DATE: NOVEMBER 30, 2024**

Always verify licenses online at [MyFloridaLicense.com](http://MyFloridaLicense.com)



Do not alter this document in any form.

This is your license. It is unlawful for anyone other than the licensee to use this document.

**Vern Roberts Environmental Training, Inc.**  
13987 94<sup>th</sup> Avenue N Seminole, FL 33776  
727-239-1445

Certifies that

**ORIE VOIGTMANN**

Has satisfactorily completed the requisite training for asbestos accreditation under TSCA TITLE II, EPA Model Accreditation Plan (40CFR763 E) for the 4-hour Inspector (Survey & Mechanical) Refresher Course on 7/13/2022, and in testimony whereof, we do confer this certificate at Seminole, Florida on 7/13/2022.

Date of Course: 7/13/2022 Expiration Date 7/13/2023  
Certificate # 07132202AM  
Course # FL49-0006322 Provider # FL49-0003810

*INSTRUCTOR*