

Quoted for: City of New Port Richey, FL

Customer Contact:

Phone: / Email:

Quoted by: Josh Stone

Phone: (919) 528-8070 / Email: josh.stone@altec.com

Altec Account Manager: Bud Welch

REFERENCE ALTEC MODEL

LR756RM	Overcenter Articulating Aerial Device (Insulated)	\$154,615
---------	---	-----------

(A.) SOURCEWELL OPTIONS ON CONTRACT (Unit)

1	LR756RM-US58	58' Boom Height (LR758-RM)	\$1,161
2			
3			
4			

(A1.) SOURCEWELL OPTIONS ON CONTRACT (General)

1	SPOT3	FOUR (4) POINT STROBE SYSTEM (LED)	\$573
2			
3			
4			
5			
6			
7			
8			
SOURCEWELL OPTIONS TOTAL:			\$156,349

(B.) OPEN MARKET ITEMS (Customer Requested)

1	UNIT		
2	UNIT & HYDRAULIC ACC		
3	BODY		
4	BODY & CHASSIS ACC		
5	ELECTRICAL		
6	FINISHING		
7	CHASSIS	2021 Freightliner M2-106 4x2 Auto, 26000 GVWR	
8	OTHER		
OPEN MARKET OPTIONS TOTAL:			\$0

SUB-TOTAL FOR UNIT/BODY/CHASSIS: \$156,349
Delivery to Customer: \$1,358
TOTAL FOR UNIT/BODY/CHASSIS: \$157,707

(C.) ADDITIONAL ITEMS (items are not included in total above)

1			
2			
3			
4			

****Pricing valid for 45 days****

NOTES

PAINT COLOR: White to match chassis, unless otherwise specified

WARRANTY: Standard Altec Warranty for Aerials and Derricks - One (1) year parts warranty One (1) year labor warranty Ninety (90) days warranty for travel charges (Mobile Service) Limited Lifetime Structural Warranty. Chassis to include standard warranty, per the manufacturer.

TO ORDER: To order, please contact the Altec Account Manager listed above.

CHASSIS: Per Altec Commercial Standard

DELIVERY: No later than **300-330** days ARO, FOB Customer Location

TERMS: Net 30 days

BEST VALUE: Altec boasts the following "Best Value" features: Altec ISO Grip Controls for Extra Protection, Only Lifetime Warranty on Structural Components in Industry, Largest Service Network in Industry (Domestic and Overseas), Altec SENTRY Web/CD Based Training, Dedicated/Direct Gov't Sales Manager, In-Service Training with Every Order.

TRADE-IN: Equipment trades must be received in operational condition (as initial inspection) and DOT compliant at the time of pick-up. Failure to comply with these requirements, may result in customer bill-back repairs.

BUILD LOCATION: CREEDMOOR, NC