


Roof



Roof Photos (continued)





Upstairs Sleeping Quarters Ceiling

The ceiling in most of the upstairs and within the Station are water stained. Much of this is due to the condition of the roof.





